

# TOTO

# "EGO II" CROSS HANDLE COMBINATION SHOWER SET TX446SEC

# **SPECIFICATIONS**





## **OPERATING CONDITIONS**

- 1. Water supply pressure: 0.05 ~ 0.75 MPa.
- 2. Ensure that water supply is clean ( No Sand, Dirt, Etc.).


#### **MAINTENANCE**


Always wipe chrome plated area with dry soft cloth, and sometimes wipe it with cloth soaked in mild soap.

# **INSTALLATION**

MOUNT CONNECTORS PARALLEL WITH
THE WALL
Hot
Water
Supply

150
Leg





## TROUBLESHOOTING

PROBLEM	CHECK POINT	SOLUTION
Water leaks around the handle	1	Tighten
Flow Regulator Inside (Don't Remove)		

CERAMIC HEAD WORK

# **ATTENTION**

- 1. Use of abrasive cleaning material such as; detergents containing hydrochloric acids, thinner, polishing powder, and nylon brush is not recommended.
- 2. Flow Regulator should not be remove because it could damage the system

**S06491M** R2